

OFFICIAL NOTICE

Boquete Council questions ASEP on outages and phone service

When	2026-09-28
Where	Boquete Municipal Council
Source	juntapalmira_ig
Published	2026-09-28 19:45-05:00
Discovered	2026-09-29 15:32-05:00
Link	https://www.instagram.com/p/Dd2gMe1g36_

Summary

At the Boquete Municipal Council session, the Palmira representative questioned ASEP about frequent power outages, dangerously low-hanging utility cables across the district, and poor mobile phone coverage in Palmira and other communities.

Full text (English)

Today we took part in the session of the Boquete Municipal Council, where we had the chance to listen to and question the ASEP Secretariat. Our participation focused on three main points: a. The constant power outages that affect the district's economy and cause damage that is rarely compensated. b. The current state of electricity, telephone and internet cabling throughout the district, with hundreds of cables installed at heights even below 3.5 metres, which is a risk and could be a life-or-death matter in emergencies where firefighters cannot get their trucks into communities. c. The very poor mobile phone service received by corregimientos such as Palmira and other communities, due to the lack of antennas covering those areas. Finally, I stressed the importance of ASEP following up with these companies so they comply with the law and ensure the quality of public services.

Original (es)

El día de hoy participamos en la Sesión del Concejo Municipal de Boquete...

El día de hoy participamos en la Sesión del Concejo Municipal de Boquete, donde tuvimos la oportunidad de escuchar y hacer consultas a la Secretaría de la ASEP. En nuestro caso, nuestra participación fue enfocada en tres aspectos principales: a. Los constantes apagones eléctricos que afectan la economía del distrito y que causan daños rara vez resarcidos. b. El estado actual del cableado de electricidad, telefonía e internet, a lo largo del distrito, siendo que actualmente se encuentran cientos de cables instalados a alturas incluso menores de los 3.5 metros de altura. Lo cual es un riesgo y puede ser una situación de vida o muerte en casos de emergencia donde los bomberos necesiten pasar a las comunidades y sus camiones no puedan entrar. c. El pésimo servicio de telefonía móvil que reciben corregimientos como Palmira, y otras comunidades, por la falta de antenas que cubran satisfactoriamente esas áreas. Finalmente, hice énfasis en la importancia de que la ASEP dé seguimiento a estas empresas para que cumplan las leyes y aseguren la calidad de los servicios públicos.