

OFFICIAL NOTICE

ASEP keeps monitoring electricity service after the earthquake

When	No date given
Where	Panama (nationwide)
Source	asep
Published	2026-10-20 13:05-05:00
Discovered	2026-10-20 20:00-05:00
Link	https://asep.gob.pa/asep-mantiene-vigilancia-sobre-el-servicio-electrico-tras-el-sismo/

Summary

Panama's public services authority ASEP says it continues to supervise power supply following the 9 October earthquake, visiting ENSA and Naturgy operations centres to check network conditions and response to new incidents.

Details (summary of the article)

ASEP, the national public services authority, reports it is still overseeing the electricity service after the 9 October earthquake, to verify continuity of supply and prompt attention to any new incident. General Administrator Zelmar Rodríguez Crespo and her team visited the operations centres of distributors ENSA and Naturgy (the latter serves Chiriquí) to review damage response, network operating conditions and the measures taken to keep service running. She said the priority is a safe and continuous service for users and that supervision will continue. One of the hardest hit points was Isla Cañas in Los Santos, where power was restored after the submarine cable feeding the community was repaired. With aftershocks continuing and recent heavy rain, ASEP says it will keep checking that distributors maintain service quality and continuity.

Original (es)

ASEP MANTIENE VIGILANCIA SOBRE EL SERVICIO ELÉCTRICO TRAS EL SISMO

La Autoridad Nacional de los Servicios Públicos (ASEP) mantiene la fiscalización del servicio eléctrico tras el sismo registrado el pasado 9 de octubre, con el objetivo de verificar la continuidad del suministro y la atención oportuna de cualquier nueva incidencia. Como parte de estas acciones, la Administradora General, Zelmar Rodríguez Crespo, junto a [...]