

## URGENT OFFICIAL NOTICE

# Road edge collapse in Jaramillo Centro - drive with care

|            |                                                                                               |
|------------|-----------------------------------------------------------------------------------------------|
| When       | 2026-10-21                                                                                    |
| Where      | Jaramillo Centro, Boquete                                                                     |
| Source     | juntajaramillo_ig                                                                             |
| Published  | 2026-10-21 15:53-05:00                                                                        |
| Discovered | 2026-10-21 16:00-05:00                                                                        |
| Link       | <a href="https://www.instagram.com/p/DexT4czS-HI">https://www.instagram.com/p/DexT4czS-HI</a> |

### Summary

The Jaramillo Junta Comunal warns drivers to be careful on a stretch of road in Jaramillo Centro where the shoulder has collapsed; the area is marked with caution tape and a flag.

### Full text (English)

CAUTION WHEN DRIVING ALONG THE ROAD IN THIS SECTOR OF JARAMILLO CENTRO. We ask drivers to drive with caution in this sector of Jaramillo Centro. Photos show a washed-out/collapsed section at the road edge, cordoned off with caution tape.

### Original (es)

⚠PRECAUCIÓN AL MANEJAR POR LA VÍA EN ESTE SECTOR DE JARAMILLO CENTRO⚠